

Standard

Initial
 Re-Inspection
 Kiddie
 Coaster
 Other

**OHIO DEPARTMENT OF AGRICULTURE
 AMUSEMENT RIDE SAFETY DIVISION
 8995 E.MAIN STREET
 REYNOLDSBURG, OHIO 43068
 Phone 614-728-6280 Fax 614-728-6416**

COMPANY CEDAR POINT/ CASTAWAY BAY
Ride TOP THRILL DRAGSTER
Plate#/Sticker# 0216/355
LOCATION 1 CAUSEWAY DRIVE, SANDUSKY, Ohio, 44870, Erie
MFG INTAMIN
Serial # 4089
Date 05/14/2021
Inspector(s) Ronald Dean, Paul Linnemeier, Joseph Mayer, Jon Kaufman

INSPECTIONS HISTORY

- | | | |
|---|--|-----|
| 1 | Since ODA's last inspection has any third-party entity or entities inspected this ride? | Yes |
| 2 | Since ODA's last inspection have you received any communication, including bulletins, recommendations, or safety orders, from the manufacturer or entities responsible for parts or service regarding the safety of this ride? | Yes |
| 3 | Since ODA's last inspection have any modifications been made to this ride that has altered the original manufacturer's drive system or operational specifications? | Yes |

LOCATION & INSTALLATION

- | | | |
|----|--|--------------|
| 4 | No visible adjacent hazards and/or interference | Satisfactory |
| 5 | In level position where applicable | Satisfactory |
| 6 | Blocked & jacked | Satisfactory |
| 7 | Anchored, braced & guyed | Satisfactory |
| 8 | Motors, belts & cables guarded | Satisfactory |
| 9 | Stairs & walkways-no obvious hazards | Satisfactory |
| 10 | Fencing, railings and gates in place | Satisfactory |
| 11 | Fuels stored in proper location & area free of spills | Satisfactory |
| 12 | No visible unsecured items | Satisfactory |
| 13 | No visible unguarded pinch points or hazardous projections | Satisfactory |
| 14 | Operating at designated speed (RPM) | N/A |

STRUCTURAL

- | | | |
|----|---|--------------|
| 15 | Visual appearance indicates proper assembly | Satisfactory |
| 16 | Visibly free of cracks or excessive wear | Satisfactory |
| 17 | No missing bolts, or bolts of improper grade | Satisfactory |
| 18 | Pins & retainers in place | Satisfactory |
| 19 | Alignment, including sheaves & cables are satisfactory | Satisfactory |
| 20 | Cables, chains,belts,gearing, and bearings indicate no excessive wear | Satisfactory |
| 21 | Motors, clutches & controls functioning when viewed | Satisfactory |
| 22 | Brakes & stops functional | Satisfactory |
| 23 | Hydraulic system shows no excessive wear | Satisfactory |
| 24 | Air system functional | Satisfactory |

TUB & VEHICLE

- | | | |
|----|--|--------------|
| 25 | Latches operate | Satisfactory |
| 26 | Ride vehicle/tub attached to ride structure | Satisfactory |
| 27 | Restraints in place and functional | Remarks |
| 28 | Skin visually free of unrepaired cracks & damage | Satisfactory |
| 29 | Seat coverings acceptable and secure | Satisfactory |
| 30 | Back up latches present & functional | Satisfactory |
| 31 | Wheels & tires-no excessive wear | Satisfactory |
| 32 | Signage/identification in place | Satisfactory |

ELECTRICAL

- | | | |
|----|--|--------------|
| 33 | Ride transformer & generators guarded, ground rod connected | Satisfactory |
| 34 | Electronic testing device indicates no stray voltage to fence/platform | Satisfactory |
| 35 | Insulation on wires & cables shows no excessive wear | Satisfactory |
| 36 | No loose cables detected at plugs or boxes | Satisfactory |
| 37 | Electrical boxes have covers, latches & signs | Satisfactory |
| 38 | Switches & controls operational | Satisfactory |
| 39 | No unattached, unconnected or unguarded lighting detected | Satisfactory |
| 40 | Electrical supply source | N/A |

Portable Generator
 Utility Power
 N/A


MISCELLANEOUS

- | | | |
|----|---|--------------|
| 41 | OTHER | Remarks |
| 42 | Owner/Agent has read and understood the codes and standards listed on this form | Satisfactory |

My signature certifies that I have read the Owner/Agent information. Further, to the best of my knowledge and belief, I will fully comply with all laws and rules for each ride that is operated.



 Owner



 ODA Inspector

Owner /Agent Notice

The owner of amusement ride(s) is required to abide by all applicable codes, standards and rules and provide necessary equipment and documents which include but are not limited to:

1. Signage OAC 901:9 - 1 - 07
2. Electrical Grounding/Requirements OAC 901:9-1-06(C) and (E)
3. Fire Extinguishers OAC 901:9 - 1 - 06 (H)
4. Maintenance Repair and Inspection Documentation ORC 1711.55(A) OAC 901:9-1-04 and OAC 901:9-1-05
5. Operator Training Documentation OAC 901:9 - 01 - 06(B) and (I)
6. Proper Anchoring OAC 901: 9 - 1 - 04 (A)

The Amusement ride cannot operate until the items listed are in full compliance.

Disclaimer: This is a visual inspection(s) meant to regulate compliance with applicable law as of the time and day of this inspection. The electrical portion of this inspection is not intended to be an electrical safety inspection pursuant to ORC Chapter 3783. The owner remains responsible under Ohio Law for maintaining the safety of the ride(s) and ride environment.

COMPLIANCE ORDER/REMARKS

THE FOLLOWING ALTERATIONS, CHANGES OR REPAIRS HEREINAFTER SET FORTH MUST BE MADE IN ORDER TO BRING THIS EQUIPMENT INTO CONFORMITY

LINE ITEM	REQUIREMENTS	DESCRIPTION	DATE COMPLIANCE DUE
1	American Testing, Wagner Consultants	General Comments	
2	Hydraulic upgrade	General Comments	
3	Hydraulic Propulsion System upgrade	General Comments	
27	Black Cherry car 2 Right Rear Lapbar cylinder soft repair, before operation and by 5/15/21 Lap Bar Cylinder Creep Test must be completed before operation and by 5/15/21	Date of Compliance	5/15/2021
41	NDT Confirmed	General Comments	

WHEN REQUIREMENTS ARE COMPLETED, CERTIFY COMPLIANCE BY GOING TO AMUSEMENT RIDE'S WEB PORTAL.
FAILURE TO COMPLY MAY RESULT IN THE REVOCATION OF YOUR PERMIT TO OPERATE AND/OR FINES UP TO \$5000.